

# CONVERSION CHART

## FRACTIONS-DECIMALS-MILLIMETERS

	<u>Decimal</u>	<u>MM</u>		<u>Decimal</u>	<u>MM</u>	
	1/64----	.0156	0.396	33/64--	.5156	13.096
1/32-----	.0312	0.793	17/32-----	.5312	13.493	
	3/64----	.0468	1.190	35/64--	.5468	13.890
1/16-----	.0625	1.587	9/16-----	.5625	14.287	
	5/64----	.0781	1.984	37/64--	.5781	14.684
3/32-----	.0937	2.381	19/32-----	.5937	15.081	
	7/64----	.1093	2.778	39/64--	.6093	15.478
1/8-----	.125	3.175	5/8-----	.625	15.875	
	9/64----	.1406	3.571	41/64--	.6406	16.271
5/32-----	.1562	3.968	21/32-----	.6562	16.668	
	11/64--	.1718	4.365	43/64--	.6718	17.065
3/16-----	.1875	4.762	11/16-----	.6875	17.462	
	13/64--	.2031	5.159	45/64--	.7031	17.859
7/32-----	.2187	5.556	23/32-----	.7187	18.256	
	15/64--	.2343	5.953	47/64--	.7343	18.653
1/4-----	.250	6.350	3/4-----	.750	19.050	
	17/64--	.2656	6.746	49/64--	.7656	19.446
9/32-----	.2812	7.143	25/32-----	.7812	19.843	
	19/64--	.2968	7.540	51/64--	.7968	20.240
5/16-----	.3125	7.937	13/16-----	.8125	20.637	
	21/64--	.3281	8.334	53/64--	.8281	21.034
11/32-----	.3437	8.731	27/32-----	.8437	21.431	
	23/64--	.3593	9.128	55/64--	.8593	21.828
3/8-----	.375	9.525	7/8-----	.875	22.225	
	25/64--	.3906	9.921	57/64--	.8906	22.621
13/32-----	.4062	10.318	29/32-----	.9062	23.018	
	27/64--	.4218	10.715	59/64--	.9218	23.415
7/16-----	.4375	11.112	15/16-----	.9375	23.812	
	29/64--	.4531	11.509	61/64--	.9531	24.209
15/32-----	.4687	11.906	31/32-----	.9687	24.606	
	31/64--	.4843	12.303	63/64--	.9843	25.003
1/2-----	.500	12.700	1-----	1.000	25.400	